

DEC 26 2007

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicants : Charles E. Chang, et al.)
Patent No. : 7,127,391)
Issued : October 24, 2006)
Appl. No. : 10/720,000)
Filed : November 20, 2003)
For : METHOD AND APPARATUS)
FOR SLICE POINT)
DETERMINATION)

COPIE
I hereby certify that this correspondence and all
marked attachments are being deposited with the
United States Postal Service as first-class mail in an
envelope addressed to: Attn: Certificate of
Corrections Branch, Commissioner for Patents, P.O.
Box 1450, Alexandria, VA 22313-1450, on

December 19, 2007

C. Miller
Chad W. Miller, Reg. No. 44,943

REQUEST FOR CERTIFICATE OF CORRECTION

Attn: Certificate of Corrections Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Dear Sir:

Enclosed for filing is a Certificate of Correction with respect to the above-referenced patent. The error on the Figure 2 of the patent, which is cited in the Certificate of Correction, was incurred through a mistake on the part of the Patent Office, and therefore a fee is not required in accordance with 37 C.F.R. Section 1.322. Applicants respectfully submit that these mistakes do not involve changes that would constitute new matter or require reexamination of the patent.

*Certificate
of Correction
DEC 31 2007*

Figure 2. DEMUX 220 should contain three (3) dots between the two bottom most output arrows.


Figure 2. MUX 230 should contain three (3) dots between the two bottom most input arrow

Patent No. : 7,127,391
Issued : October 24, 2006

Respectfully submitted,

Dated: 12/19/07

By:



Chad W. Miller
Attorney of Record
Registration No. 44,943
Weide & Miller, Ltd.
Bank of Nevada Building, Suite 530
7251 W. Lake Mead Blvd.
Las Vegas, NV 89128
(702) 382-4804 (Pacific time)

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. : 7,127,391

DATED : October 24, 2006

INVENTOR(S) : Charles E. Chang, et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Figure 2. DEMUX 220 should contain three (3) dots between the two bottom most output arrows.

Figure 2. MUX 230 should contain three (3) dots between the two bottom most input arrows.

MAILING ADDRESS OF SENDER (Please do not use customer number)

PATENT NO. _____

No. of additional copies _____

